

1" x 30" bar. In a Lincoln County surveyor's field book, it is stated that in 1965 a 1" x 24" iron pipe was set above the corner. No signature is attached to the statement.

We found the 1" x 30" iron bar recorded by Brown noting that a portion of the bar was bent. We also found a 1" x 24" iron pipe approximately 10 inches southeast of the iron bar. This must be the iron pipe that is mentioned in the County Surveyor's field book in 1965. We found the Reference Monument (termed Witness Corner) set by Brown, 46.6' southeast of the iron bar but could not locate the Reference Monument he set northwest of the corner. This intersection may have been cut down by road construction and in particular the Northwest Corner of the intersection. It appears to have been cut back to daylight the intersection. We did not locate the marked brick as recorded by Brown at the base of the iron bar. We untied the monuments and, with a backhoe, dug an area approximately 7' x 10' x 4-5' deep, about and under the area where we found the two monuments. We did not find any of the previously recorded monumentation by P.G. Meyer under the iron bar or iron pipe.

At the approximate location of the Northwest Corner of the Northeast Quarter of the Northeast Quarter of said Section 24, monumented by P. G. Meyer in 1892, we dug a large area with a backhoe, but did not find the recorded stone.

The North Quarter Corner of Section 24 was reestablished by P.G. Meyer in 1892 and monumented with a line rock. Brown, in Application Survey 616, found the monumentation by P. G. Meyer and rebuilt the corner with a 1" x 30" iron bar. In 1987 we located a temporary position for this corner based upon the Meyer and Brown surveys, we dug an area approximately 7 feet north-south and 15 feet east-west and approximately 4 to 5 feet deep but could not find the monumentation recorded by Brown or Meyer. We did not find any reference monuments for this corner. We did find an unrecorded monument (1" x 12" iron pipe) approximately 1.7 feet north and approximately 0.8 feet west of the location for the North Quarter Corner. I did not accept this unrecorded monument for the North Quarter Corner of Section 24 because of its position how accurate P.G. Meyer surveyed. In 1988, Richard J. Nosky, Lincoln County Surveyor re-established this corner midway and on line between the Northwest and Northeast Corners of Section 24 setting a 5/8" rebar with an aluminum cap. In 2006 we found this monumented corner.

778-783 $\frac{1}{2}$

778-805 $\frac{3}{4}$